



150.





FIG. 6

output

FIG. 5




FIG. 7A

P1 = "0"	$V(C_1) = V_{ref}$	$Q(C_1) = C \cdot V_{ref}$
P2 = "0"	$V(C_2) = 0$	$Q(C_2) = 0$
P3 = "1"	$V(C_3) = 0$	$Q(C_3) = 0$
	$V(C_4) = 0$	$Q(C_4) = 0$




FIG. 7B

P1 = "1"	$V(C_1) = V_{ref}/4$	$Q(C_1) = C \cdot V_{ref}/4$
P2 = "0"	$V(C_2) = V_{ref}/4$	$Q(C_2) = C \cdot V_{ref}/4$
P3 = "0"	$V(C_3) = V_{ref}/4$	$Q(C_3) = C \cdot V_{ref}/4$
	$V(C_4) = V_{ref}/4$	$Q(C_4) = C \cdot V_{ref}/4$




FIG. 7C

P1 = "0"	$V(C_1) = V_{ref}/4$	$Q(C_1) = C \cdot V_{ref}/4$
P2 = "1"	$V(C_2) = V_{ref}/4$	$Q(C_2) = C \cdot V_{ref}/4$
P3 = "0"	$V(C_3) = V_{ref}/4$	$Q(C_3) = C \cdot V_{ref}/4$
	$V(C_4) = V_{ref}/4$	$Q(C_4) = C \cdot V_{ref}/4$




FIG. 10



800




FIG. 35